

STEEL TUBE INSTITUTE

HSS Design Manual, Volume 3 Connections at HSS Members

TABLE OF CONTENTS

INTRODUCTION TO DESIGN OF SHEAR AND MOMENT CONNECTIONS FOR HSS	1
LIMIT STATES	2
Matrix of Limit States for Connections to HSS Columns	3
WIDE-FLANGE BEAM SHEAR CONNECTIONS AT HSS COLUMNS	4
Single Plate Connections.....	4
Table 3-3.1 Minimum Thickness Table for Punching Shear in Single Plate Connections.....	5
Table 3-3.2 Single Plate Connection Tables.....	6
Single Angle Connections.....	8
Table 3-3.3 Single Angle Connection Tables	10
Double Angle Connections.....	12
WT Connections.....	13
Table 3-3.4 WT Connection Tables.....	14
Unstiffened Seat Connections.....	16
Stiffened Seat Connections	17
Through-Plate Shear Connections	17
High Shear Load Connections	18
CONNECTIONS FOR HSS BEAMS.....	19
SHEAR CONNECTION EXAMPLES.....	23
WF Beam to HSS Column Single Plate Connection Example.....	23

WF Beam to HSS Column Single Angle Connection Example.....	26
WF Beam to HSS Column Double Angle Connection Example.....	30
WF Beam to HSS Column WT Connection Example.....	33
WF Beam to HSS Column Unstiffened Seat Connection Example.....	37
WF Beam to HSS Column Stiffened Seat Connection Example	41
WF Beam to HSS Column Through-Plate Connection Example.....	47
HSS Beam to HSS Column Double Shear Plate Connection Example	51
HSS Beam to HSS Column Seated Connection with Top Angle Example	56
HSS Beam to HSS Column End Plate Connection	60
Beam to HSS Column High Shear Load Connection Example.....	66
MOMENT CONNECTIONS AT HSS COLUMNS	74
Continuous Beam Over HSS Column Connections.....	74
Through-Plate Moment Connections.....	75
Cut-out / Collared Plate Moment Connections.....	75
Welded Tee Flange Moment Connections	76
End Plate Moment Connections	76
Diaphragm Plate Moment Connections	77
Directly Welded Connections.....	77
MOMENT CONNECTION EXAMPLES	78
Continuous Beam Over HSS Column Connection Example.....	78
Through-Plate Moment Connection Example.....	88
Cut-Out/Collared Plate Moment Connection Example	97
Welded Tee Flange Moment Connection Example	106
Directly Welded Moment Connection Example.....	114
Diaphragm Plate Moment Connection Example.....	117